



7575 N.W. 74th Avenue Miami, Florida 33166
 T: (305) 885 - 8689 F: (305) 489 - 0673
 www.seauto.com

SUPER HOT PRODUCTS


CHECK OUR PRICES!
We just can't be beat!

Bulletin # 1045_EU

GM Pressure Switch Manifolds These won't last long!

4L60-E

Part #: SE77943
 OE #: 24219581
 This is the latest design version that covers all model years from 1993 to present. Heavy duty backing plate and improved o-rings prevent high pressure blow-by and ensure long term durability. 50 pieces per case.



\$19.50

4L80-E

Part #: SE34657
 OE #: 24222077
 Our pressure switch manifold fits both the 4L80-E and the 4L85-E transmissions built from 1991 to present. We have improved the o-ring mounting style to prevent sealing ring deformation that ultimately leads to leaking and blow-by.



\$29.50

4T65-E

Part #: SE84987
 OE #: 24223197
 This is the "early" style 4-prong switch covering model years from 1997 to 2002. The second version switch (2003-on) is in development but not yet available. Heavy duty backing plate and improved o-ring system to prevent high pressure blow-by. The manifold is the answer to premature switch failure.



\$42.50

4T80-E

Part #: SE72951
 OE #: 24200770
 This is the latest design version that covers all model years from 1993 to 1999. The same design characteristics are built into this manifold to ensure perfect performance. You don't want to do this transmission twice, do it right the first time! 25 pieces per case.



\$46.50

Southeast Worldwide Manufacturers has sent you this information because of your prominent position within the industry. If you feel that you have received this in error, or would like to be removed from special announcements, please fax back toll free, with your name and fax number to 1-800-836-6845.